

| STATUS | PROVIDER | AHIB # | HR S | | TITLE | EXPIRATION | Subject Area |
|----------|------------|--------------|------|-----------|--|------------|---|
| APPROVED | ABC | CE-2016-07 | 2 | Classroom | Report Writing | 6/22/2017 | Report Writing |
| APPROVED | ABC | CE-2016-08 | 6 | Classroom | Exterior Inspection | 6/22/2017 | Exteriors |
| APPROVED | ABC | CE-2016-09 | 6 | Classroom | Roofing Inspection | 6/22/2017 | Roofing |
| APPROVED | PHII | CEO-2016-10a | 2 | Online | Advanced Home Inspection-Module 1: Structure, Exteriors, and Roofing | 3/30/2017 | Structural Systems |
| APPROVED | PHII | CEO-2016-10b | 1 | Online | Advanced Home Inspection-Module 1: Structure, Exteriors, and Roofing | 3/30/2017 | Exteriors |
| APPROVED | PHII | CEO-2016-10c | 1 | Online | Advanced Home Inspection-Module 1: Structure, Exteriors, and Roofing | 3/30/2017 | Roofing |
| APPROVED | PHII | CEO-2016-11a | 2 | Online | Advanced Home Inspection-Module 2: Plumbing and Electrical | 3/30/2017 | Plumbing |
| APPROVED | PHII | CEO-2016-11b | 2 | Online | Advanced Home Inspection-Module 2: Plumbing and Electrical | 3/30/2017 | Electrical |
| APPROVED | PHII | CEO-2016-12 | 4 | Online | Radon Measurement Certification | 3/30/2017 | General Classroom Credit |
| APPROVED | ASHI | CEO-2016-01 | 2 | Online | Improve Your Report Writing | 6/22/2017 | Report Writing |
| APPROVED | ASHI | CEO-2016-02 | 2 | Online | Causes, Symptoms and Solutions to Common Foundation Problems | 6/22/2017 | Structural Systems |
| APPROVED | ASHI | CEO-2016-03a | 1 | Online | Basic Residential Heating and Cooling | 6/22/2017 | Heating |
| APPROVED | ASHI | CEO-2016-03b | 1 | Online | Basic Residential Heating and Cooling | 6/22/2017 | Cooling |
| APPROVED | ASHI | CEO-2016-04 | 2 | Online | High Efficiency Gas Furnace | 6/22/2017 | Heating |
| APPROVED | ASHI | CEO-2016-05 | 2 | Online | Inspecting Old Homes from the Ground Up | 6/22/2017 | Structural Systems |
| APPROVED | ASHI | CEO-2016-06 | 2 | Online | Asphalt Shingles and Flat Roofs | 6/22/2017 | Roofing |
| APPROVED | ASHI | CEO-2016-07 | 2 | Online | Metal, Slate, Specialty Roofing and Wood Shingles | 6/22/2017 | Roofing |
| APPROVED | ASHI | CEO-2016-08 | 2 | Online | Chimney Inspections | 6/22/2017 | Fireplaces and Solid Burning Appliances |
| APPROVED | ASHI | CEO-2016-09 | 2 | Online | Electric Service Inspections | 6/22/2017 | Electrical |
| APPROVED | ASHI | CE-2016-10 | 2 | Classroom | Analyzing and Finding Hard to Find Leaks | 7/13/2017 | Plumbing |
| APPROVED | ASHI | CE-2016-11 | 2 | Classroom | Inspection & Development of Modern Plumbing & Sewer Systems | 7/13/2017 | Plumbing |
| APPROVED | ASHI | CE-2016-12 | 2 | Classroom | Grounding and Bonding/Multi-wire Branch Circuits | 7/13/2017 | Electrical |
| APPROVED | ASHI | CE-2016-13 | 2 | Classroom | Making Connections: Pipes & Fittings, Application & Installation | 7/13/2017 | Plumbing |
| APPROVED | ASHI | CE-2016-14 | 2 | Classroom | Taking a Closer Look at Electrical Inspections | 7/13/2017 | Electrical |
| APPROVED | ASHI | CE-2016-15 | 2 | Classroom | Built In Appliance Inspection | 7/13/2017 | General Classroom Credit |
| APPROVED | ASHI | CE-2016-16 | 2 | Classroom | Inspection Old Houses: the Good, the Bad and the Ugly (Part 1) | 7/13/2017 | General Classroom Credit |
| APPROVED | ASHI | CE-2016-17 | 2 | Classroom | Inspection Old Houses: the Good, the Bad and the Ugly (Part 2) | 7/13/2017 | General Classroom Credit |
| APPROVED | ASHI | CE-2016-18 | 2 | Classroom | The 10 Most Common Problems with Masonry Fireplaces & Chimneys | 7/13/2017 | Fireplaces and Solid Burning Appliances |
| APPROVED | HITA | CE-2016-19 | 4 | Classroom | Inspecting Asphalt Roofs - Analyzing and Finding Leaks | 8/10/2017 | Roofing |
| APPROVED | HITA | CE-2016-20 | 4 | Classroom | Flat & Specialty Roofs | 8/10/2017 | Roofing |
| APPROVED | HITA | CE-2016-21 | 4 | Classroom | Exterior Insulation Finish Systems (EIFS) | 8/10/2017 | Insulation and Ventilation |
| APPROVED | HITA | CE-2016-22 | 4 | Classroom | Water Heater Inspection | 8/10/2017 | Plumbing |
| APPROVED | InterNACHI | CE-2016-23 | 8 | Classroom | How to Inspect for Moisture Intrusion | 11/1/2017 | Structural Systems |
| APPROVED | InterNACHI | CE-2016-24 | 2 | Classroom | How to Inspect Tile Roofs | 11/1/2017 | Roofing |
| APPROVED | InterNACHI | CE-2016-25 | 4 | Classroom | How to Perform Roof Inspections | 11/1/2017 | Roofing |
| APPROVED | InterNACHI | CEO-2016-26 | 4 | Online | How to Perform Roof Inspections | 11/1/2017 | Roofing |
| APPROVED | InterNACHI | CE-2016-27 | 2 | Classroom | 10 Steps to Performing a Roof Inspection | 11/1/2017 | Roofing |
| APPROVED | InterNACHI | CEO-2016-28 | 2 | Online | 10 Steps to Performing a Roof Inspection | 11/1/2017 | Roofing |
| APPROVED | InterNACHI | CEO-2016-29 | 8 | Online | Defect Recognition and Report Writing | 11/1/2017 | Report Writing |
| APPROVED | InterNACHI | CEO-2016-30 | 14 | Online | Attic, Insulation, Ventilation and Interior | 11/1/2017 | Insulation and Ventilation |
| APPROVED | InterNACHI | CEO-2016-31 | 4 | Online | How to Inspect Fireplaces, Stoves and Chimneys | 11/1/2017 | Fireplaces and Solid Burning Appliances |
| APPROVED | InterNACHI | CEO-2016-32 | 4 | Online | How to Perform Residential Electrical Inspections | 11/1/2017 | Electrical |
| APPROVED | InterNACHI | CEO-2016-33 | 4 | Online | How to Inspect Water Heater Tanks | 11/1/2017 | Plumbing |

